


COLUMBINE W&S DISTRICT

Sewer Pipe Installed By Year



Sewer Pipe Installed By Year

	6		8						10			12		Total
	C-900 POLYVINYL CHLORIDE PIPE	C-900 POLYVINYL CHLORIDE PIPE	CAST IRON PIPE	CURED IN PLACE PIPE	Ductile Iron Pipes	Polyvinyl Chloride	SUPPLIED VERTICAL CLAY PIPE	Vitrified Clay Pipes	CURED IN PLACE PIPE	SUPPLIED CLAY PIPE	Vitrified Clay Pipes	C-900 POLYVINYL CHLORIDE PIPE	CURED IN PLACE PIPE	
1955	0	0	0	0	0	0	0	1,698	0	0	412	0	0	2,110
1971	0	0	0	0	0	0	0	2,460	0	0	0	0	0	2,460
1972	0	0	0	0	0	0	0	115	0	0	0	0	0	115
1973	0	0	165	0	54	608	0	23,247	0	0	94	0	0	24,168
1980	0	0	0	0	0	5,779	0	0	0	0	0	0	0	5,779
1988	0	0	0	0	0	0	0	2,040	0	0	0	0	0	2,040
1999	0	0	0	7,697	0	0	772	0	423	783	0	0	0	9,675
2000	0	0	0	0	0	0	0	0	710	0	0	0	4,096	4,806
2001	1,626	3,420	0	0	0	0	0	0	0	0	0	2,500	0	7,546
2002	0	1,148	0	0	0	0	0	0	0	0	0	0	0	1,148
2007	0	0	0	1,647	0	0	0	0	0	0	0	0	0	1,647
2014	0	366	0	0	0	1,823	0	0	0	0	0	0	0	2,189
2015	0	124	0	0	0	0	0	0	0	0	0	0	0	124
2018	0	0	0	6,638	0	0	0	0	0	0	0	0	0	6,638
Total	1,626	5,058	165	15,982	54	8,210	772	29,560	1,133	783	506	2,500	4,096	70,445