


COLUMBINE W&S DISTRICT

Sewer Pipe Installed By Year



Sewer Pipe Installed By Year

	6			8						10				12			Total
	C-900 POLYVINYL CHLORIDE PIPE	C-900 POLYVINYL CHLORIDE PIPE	CAST IRON PIPE	CURED IN PLACE PIPE	Ductile Iron Pipe	Other (State (In Comments	Polyvinyl Chloride	SUPPLIED VITRIFIED CLAY PIPE	Vitrified Clay Pipe	CURED IN PLACE PIPE	Other (State (In Comments	SUPPLIED VITRIFIED CLAY PIPE	Vitrified Clay Pipe	C-900 POLYVINYL CHLORIDE PIPE	Other (State (In Comments	Polyvinyl Chloride	
1955	0	0	0	0	0	0	0	0	1,698	0	0	0	412	0	0	0	2,110
1971	0	0	0	0	0	0	0	0	2,456	0	0	0	0	0	0	0	2,456
1972	0	0	0	0	0	0	0	0	115	0	0	0	0	0	0	0	115
1973	0	0	165	0	54	0	608	0	22,625	0	0	0	94	0	0	0	23,546
1980	0	0	0	0	0	0	5,606	0	0	0	0	0	0	0	0	0	5,606
1988	0	0	0	0	0	0	0	0	2,040	0	0	0	0	0	0	0	2,040
1999	0	0	0	7,697	0	0	0	772	0	423	0	783	0	0	0	0	9,675
2000	0	0	0	0	0	0	0	0	0	0	704	0	0	0	4,103	0	4,807
2001	1,626	0	0	0	0	2,454	878	0	74	0	0	0	0	14	0	2,490	7,536
2002	0	0	0	0	0	0	1,150	0	0	0	0	0	0	0	0	0	1,150
2007	0	0	0	1,647	0	0	0	0	0	0	0	0	0	0	0	0	1,647
2014	0	0	0	0	0	366	1,823	0	0	0	0	0	0	0	0	0	2,189
2015	0	124	0	0	0	0	0	0	0	0	0	0	0	0	0	0	124
2018	0	0	0	6,637	0	0	0	0	0	0	0	0	0	0	0	0	6,637
Total	1,626	124	165	15,981	54	2,820	10,065	772	29,008	423	704	783	506	14	4,103	2,490	69,639